25X1

25X1

CLASSIFIED MESSAGE

SECRET

FILE INFO

(When Filled In)

REPRODUCTION PROHIBITED								
ACTION	1	6	11	16				
	2	7	12	17	· · · · · · ·			
	3	8	13	18				
	4	9	14	19				
	5	1,0	15	2Ø				

PAGE 2 TOPSECRET READOUT DATA SHOWS ACTUAL POSITION OF ARTICLE AT PT C TO BE 10 MM W NW OF PLANNED CRSE POSITION. THIS ERROR CONCLUDED TO BE CUASED BY STRONGER THAN FORE-CASTED WIND ON LEG B-C.

C. ALTHOUGH PILOT TURNED 30 SECONDS EARLY AT PT D. ERROR AT PT C AND WINDS STRONGER THAN FORE-CASTED CAUSED 18 NM ERROR AT PTS D AND F.

SHOW THAT PILOT NOTED ERROR AT PIS D AND F AND MADE CORRECTIONS TO THE LEFT UP TO 16 DEGREES. HOWEVER.

- THESE WERE INADEQUATE TO RETURN HIM ALL THE WAY BACK TO CRSE.
- D. THE EFFECT OF THE FIRST ERROR AT PT C CONTINUED THROUGHOUT THE FLT ALTHOUGH PILOT CORRECTIONS EVENTUALLY RETURNED HIM TO A PRECISE TRACK ON LEG U-V.
 - 3. AFTER A DETAILED STUDY OF THE MSN DATA IT IS OUR CONCLUSION THAT:
 - A. THE ERRORS WERE CUASED BY STRONGER THAN FORECASTED WINDS.
 - B. THERE WAS NO DELIBERATE ATTEMPT TO DEVIATE FROM THE PLANNED CRSE.

AM 2820 2-67

CLASSIFIED MESSAGE

SECRET

FILE INFO

(When Filled In)

		REPRODUCTION	PROHIBITED	
ACTION	1	[6]	11	16
	2	7	12	17
 	3	8	13	18
	4	9	14	19
	5	1ø	15	2ø

PAGE 3 TOPSECRET	•,	25X1
C. THE PILOT SHOWED NO LACK OF PORFICIENCY AND		
MADE WHAT HE UNDERSTANDABLY THOUGHT WERE PROPER CORRECTIONS		25X1
TO RETURN TO COURSE.		_
	-	

THAT THE ERRORS WERE A RESULT OF UMPREDICTED WINDS.

TOPSECRET

25X1

BT

#3386